

Mini Road Tour

Watab Township

Monday, November 18, 2024

Peace Rock Road - Dead Tree to remove, leaning. Cut back pines and overhangs

6765 Riverview Loop – 3 leaning trees on east side of the road. Some trimming at south end.

56th – Remove Limbs and shrubs

5th Avenue NW (Lake Andrew Area) – Clear brush around culvert posts, lots of limbs and small trees to remove and cut back.

Jasmine Loop – E Side Low hanging limb removal

Burton – Determine which large tree's to remove after survey report.

Indian – Buckthorn, tree's, Shurbs removal. Fix Leaning culvert post #13

W. Lake Road – 2 Leaning Culvert Posts, 2 Limbs East of Zelenys, Tree down on N end, Call Rau's about the tree debris left in the ROW. Red Milk can mail box post in row, note to owner to install swing away post.

Circle Pines – Tree Trimming Limbs

10th Ave NW – Limb Removal on the East Side

Lakewood Shores – W. End cut oak Limbs back to tree's. Ask land owner to cut them.

Potholes:

15th Avenue NW north of Pines Edge.

West Lake Road